



Center for Environmental Health

Keep pool closed until passing reinspection p.9

PUBLIC SWIMMING POOL INSPECTION REPORT

FACILITY NAME	Milford Woods	PERMIT NO.	1-3927
ADDRESS	3250 Ashgrove Lane, Marietta	INSPECTION DATE	5/28/2013

The items marked below by X are violations and must be corrected as noted to be in compliance with the Douglas Public Health Rules and Regulations for Swimming Pools.

1. POOL AND WATER QUALITY

- Clarity & Water Chemistry
- Proper Water Level
- Turnover Adequate, Flow Meter

available chlorine → 1 ppm pages 18-19

Cl/Br	pH: 7.4	SPA TEMPERATURE:
CYANURIC ACID:		TOTAL ALKALINITY: *

2. PUMPS, FILTRATION, TREATMENT SYSTEM

- Pumps, Filtration Adequate
- Chlorination Equipment Adequate
- Chemical Feeders Adequate
- Inlets, Outlets, Fill Spouts in good repair
- Hair & Lint Strainers Functioning Properly
- Vacuum Cleaning System
- Pump Room Neat & Clean & Well Drained
- Operational Instructions Posted
- Adequate Room to Make Repairs
- Pump Room Adequately Ventilated & Lighted

page 34 * page 16 →

COMMENTS: Raise chlorine 3ppm-5ppm

3. DECK AND POOL

- Floors, Walls, Deck, Ladders, Steps, Handrails, Boards, etc. clean and in good repair
- Night Lighting Adequate
- Adequate Refuse Storage Provided
- Deck Well Drained
- Backflow Prevention Provided to all hose bibs
- Deck Properly Marked

* page 16 →

Throw rope needed on the lifering 1/2 x width of pool or 50ft (whichever is less)

Recessed tread on steps (middle tread) at the 5ft section of the pool (middle of pool) is in need of repair on the opposite side of the 5ft end, the handrail for the steps is not secured to the pool deck - secure hand rail

Replace missing light at the 4 1/2 ft. end.

4. SAFETY PRECAUTIONS

- Proper Signage Posted
- Telephone Operational with 911 Posted
- First Aid Kit Provided
- Shepherd Hook, Life Ring & Life Line in conspicuous place
- Adequate Gas Chlorine Safety precautions
- Diving Board Meets Design Criteria

P15 →

Darken the stencil depth markers and "no diving" markers around the pool deck.

5. BATHHOUSE FACILITIES

- Floors, Walls, Ceilings & Fixtures Clean & in Good Repair
- Ventilation, Lighting Adequate
- Soap provided at shower
- Drinking Fountain available, clean & in good repair
- Food & Beverage properly handled & in approved location
- Soap, Paper Towels & Toilet Paper provided

P35 →

Rehang pool rules sign "No lifeguard on duty" sign needed at entrance of pool

6. OPERATOR AND RECORDS

- Daily Records Maintained
- Proper Test Kit Provided
- Permit Posted

reconnect phone *

PURPOSE:

<input type="checkbox"/> 1. Routine	<input checked="" type="checkbox"/> 4. Complaint
<input type="checkbox"/> 2. Follow-up	<input type="checkbox"/> 5. Other
<input type="checkbox"/> 3. Request	

7. OTHER

(See Comments) on return line

DISCUSSED WITH: [Signature]

INSPECTED BY: Kathleen Schmidt EHS II

RECHECK DATE:

8700 Hospital Drive | Douglasville, GA 30134-2264 | (770) 920-7311 | Fax (770) 920-7317

www.CobbAndDouglasPublicHealth.org

Chlorinator 35BFM

3830 S. Cobb Drive Suite 102 Smyrna, GA 30080

Environmental Health & Swimming Pool (770) 435-7815 Revised 01/19/2010 ext 5070